

# PANORAMA™ Technical Bulletin

## **Panorama™ Driver Bug Fix for DigiLinX™ Dealer Setup 1.70.03**

NetStreams has found a bug with the *Panorama* driver embedded in *DigiLinX* Dealer Setup version 1.70.03. This bug affects the function of the *Panorama* when it is connected to a *MediaLinX* MLA4000 and when less than six rooms of video are used.

If any of the rooms are empty on the display configuration of the *Panorama* in *DigiLinX* Dealer Setup version 1.70.03, dealers will need this patch.

You can install the patch by overwriting the driver.

Contact *NetStreams* Technical Support to obtain the patch and follow these steps:

1. Contact *NetStreams* Technical Support to obtain the new *Panorama.lua* driver.
2. Go to "C:\Program Files\DigiLinX Dealer Setup\upgrader\05\_07\_2007\drivers" directory and delete the old "Panorama.lua".
3. Copy the new *Panorama.lua* that you just received into the "C:\Program Files\DigiLinX Dealer Setup\upgrader\05\_07\_2007\drivers" directory.
4. Launch Dealer Setup.
5. Load your project file.
6. Send configuration files to all devices.
7. Save the project file.

This bug will be fixed with the next release of *DigiLinX* Dealer Setup 2.0.

The  
IP-Based  
Distributed  
Entertainment  
Company.

### Products Included:

*DigiLinX*

*PAN6400*

*MediaLinX™*

