

DigiLinX Dealer Setup 2.35 Release Notes

DigiLinX Dealer Setup is the configuration software for the award winning DigiLinX system from *NetStreams*.

These Release Notes cover What's New, Download and Installation instructions, Fixed issues, Known issues and workarounds, and Frequently Asked Questions for DigiLinX Dealer Setup. Please read these notes and the "How to Get Support" instructions before reporting issues to *NetStreams*.

Give us your feedback at scastelino@NetStreams.com.

What's New in DigiLinX Dealer Setup 2.35

Release Date: October 1st, 2008

New Features:

- **MotionXT Video Stream** Compression for the MLAV9300-CS (All ViewLinX support MotionXT Stream Compression)
- **Support for additional NaimNet StreamNet Connected products:** Added support for NaimNet Tuner products
- **Dealer Setup Large System Performance Improvements.** Dealer Setup works large projects dramatically faster.
- **Saving Progress Bar:** Saving a project has a progress bar now
- **Generic HVAC GUI** is now available for use in using alternate HVAC systems
- **Sensible Heat** driver support added with complete GUI
- **IP-Based Control:**TCP added as a connection option in generic ControlLinX to support IP-based control
- **International string files updated** with language updates
- **Relay services updated:** Relay services are now disabled by default and can be turned on/off.
- Two additional display buttons have been added to ViewLinX and ControlLinX devices to equal eight (matching the TheaterLinX)
- #LIST add to IR tool
- Improved startup timing on SL250 amplifier chip

Downloading and Installing

System Requirements

Before installing DigiLinX Dealer Setup, please make sure your computer meets the minimum system requirements.

Operating System

- Microsoft Windows XP SP2
- Microsoft Vista

Hardware

- Pentium 1.2 GHz or greater (*recommended: 2.0 GHz or greater*)
- 512 MB of RAM (*recommended: 1 GB or greater*)
- 120 MB of free hard drive space

Downloading DigiLinX Dealer Setup

DigiLinX Dealer Setup 2.35.00 Release Notes

DigiLinX Dealer Setup can be downloaded from the password protected dealer section of NetStreams.com. Contact marketing@NetStreams.com if you are an authorized dealer and need login credentials.

Installing DigiLinX Dealer Setup

Please note that installing DigiLinX Dealer Setup into the same directory as your current installation will *overwrite* your existing installation. You will not lose custom drivers in your drivers folder. *NetStreams* recommends backing up critical files before any DigiLinX Dealer Setup upgrade.

Removing DigiLinX Dealer Setup

You can remove DigiLinX Dealer Setup in two ways: the Add/Remove Programs icon in the Windows Control Panel, accessible through the Start Menu, or using the included Uninstall program found under Start Menu, DigiLinX Dealer Setup, Uninstall DigiLinX Dealer Setup.

Fixed Issues

The following is a list of some of the major issues addressed in DigiLinX Dealer Setup 2.35.

1. Missing sort option for macro tool added back in
2. Scroll bugs fixed in macro tool where going to bottom of list caused aberrations
3. Fixed slider bugs on SL250 devices where typing in text fields made the slider go off screen.
4. Macros fixed where Control services were missing buttons (using ID instead now)
5. ViewLinX combo boxes fixed where data was missing
6. Remove duplicating room names in project if apostrophe existed in the room name
7. Fix bug on All Songs preset for media servers where Media was capitalized, thereby breaking the SMM.
8. Fixed tab index problems on devices/system settings.
9. All Tstats added to controlData block for HVAC drivers
10. Fixed Z-order problem on "data has changed" pop-up when presets are on the stage.
11. Fixed macro up/down buttons where you can click on them repeatedly now w/o moving the mouse.
12. Color label buttons fixed to all be the same color for PVR sources
13. Bug fixed for TheaterLinX not labeling PVR source color buttons correctly
14. Fixed issue where going to full screen made foreign characters disappear
15. Panorama works Intermittently with 2.3.1- Can not switch Video
16. Panorama display Index problem, Index is off by 1
17. KeylinX source button missing after saving project
18. Multi-Room Leave or Cancel causes TL to lockup
19. The List button is not functional on PVR GUI
20. TL380 intermittent lockup, Firmware will sense situation and correct.

Known Issues

The following is a list of known issues and their associated workarounds in DigiLinX Dealer Setup 2.35. For questions about these issues, please contact *NetStreams* Technical Support (see "How to Get Support" below).

There are no additional known issues for this release. Please see past release notes for older known issues. Issues remain classified as known until fixed.

Frequently Asked Questions

- How do I get support?

Please see the section below labeled “How to Get Support.”

- I have an idea for a feature or want *NetStreams* to support a certain product, how do I submit my request?

Please send an email with your request to mleonard@NetStreams.com.

- When will you support a driver for <insert product>?

We announce driver support when a release of new drivers is within 90 days.

- When is your next DigiLinX Dealer Setup release?

We release DigiLinX Dealer Setup approximately quarterly. Our next targeted release is Late Fall 2008.

How to Get Support

NetStreams technical support group is the official support channel for all *NetStreams* products and software, including DigiLinX Dealer Setup. Support is available 7 AM to 7 PM Monday through Friday. For the fastest response time, you can email the team at support@NetStreams.com. For time-sensitive or onsite issues, you can reach them by phone at +1-866-353-3496.

Additional Resources

- [NetStreams Corporate](#)
- [NetStreams University](#)
- [NetStreams Forums](#)